



PUBLIC WORKS DEPARTMENT (B & R), HARYANA

OFFICE OF THE SUB DIVISIONAL ENGINEER
PROVINCIAL SUB DIVISION NO.-4, GURUGRAM
Email ID:- sdepsd4@gmail.com



No.

116

Dated

18/1/19

To

Guru Dronacharya Sr. Sec. School,
Sector-91, Bhangrola (Gurugram).

Subject: - Certificate Stability of the School Building.

The site has been inspected by Sh. Krishan Kumar, J.E. incharge on 18.01.2019. From physical inspection, the building is found safe. So far as structural design is concerned, Er. & Vr. R.K. Singh, Structural Consultant is responsible for the same as per Structural Stability certificate given by him on dated 30.05.2018.

DA/Nil

Sub Divisional Engineer,
Provincial Sub Division No.4,
PWD B&R Branch, Gurugram.

Endst No.

Dated

Copy of above is forwarded to Executive Engineer, Provincial Division No.II, PWD B&R Br., Gurugram for information w.r.t. his office endst. no. 279 dated 17.01.2019.

DA/Nil

Sub Divisional Engineer,
Provincial Sub Division No.4,
PWD B&R Branch, Gurugram.

Principal
Guru Dronacharya Sr. Sec School
Bhangrola (Gurugram)
CBSE Affiliation No. 531444